

Marana High Plains Effluent Recharge Project

Project Operations Photos



Photo 1 – Compliance Well HP-1, December 2001



Photo 2 – Wet well, 2003



Photo 3 - Flow meter in Cell 2, 2003



Photo 4 - Precipitation sensor, 2003



Photo 5 - Pump inlet pipes, 2003



Photo 6 - Cell 1, looking east, April 2004



Photo 7 - Cell 2, looking east, April 2004



Photo 8 - Cell 3, looking northwest, April 2004



Photo 9 - Cell 4, looking east, April 2004



Photo 10 - Equalization Basin, looking west, April 2004



Photo 11 - Cell 2, May 2005



Photo 12 - Cell 1 inlet, December 2005



Photo 13 - Cell 2, looking east, December 2005



Photo 14 - Diversion ditch near HP-1, December 2005



Photo 15 - Equalization Basin, looking south, December 2005



Photo 16 - Cell 2, looking southwest, January 2008



Photo 17 - Cell 1, looking northwest, September 2008



Photo 18 - Cell 3, looking west, September 2008



Photo 19 - Cell 4, looking east, September 2008



Photo 20 - Maintenance Road north of Cell 4, September 2008



Photo 21 - Maintenance Road south of Cell 4, September 2008



Photo 22 - Oxbow channel near east end of project