

Desert Willow Open Space – Trail Project 2018



Headcut before treatment



Headcut after treatment; zuni bowl rock structure with a one rock dam



Ponding in trail before treatment



Post-treatment, trail re-aligned to high ground on the right, depression seeded and closed. Closed trail has been converted to a water harvesting area.



Rill erosion caused by excessive equestrian use on a sloped area, pre-treatment.



Post-treatment; a series of one rock dams to slow and infiltrate stormwater.



Pre-treatment; a large gully has formed caused by run-off from upstream trails.



Post-treatment; a rock rundown to prevent further down-cutting of the gully.



Post-treatment, compacted trail ripped, native seed mix applied and signage and brush placed across the closed trail.



New vehicle and pedestrian gate at the west entrance.



New Trail Map sign at the east entrance.