



**PIMA COUNTY  
DEPARTMENT OF FINANCE & RISK MANAGEMENT**

RISK MANAGEMENT DIVISION  
130 W. Congress St., 9<sup>th</sup> Floor  
TUCSON, ARIZONA 85701-1403

|  |
|--|
| <b>Date:</b> May 28, 2014  |
| <b>Department:</b> Economic Development and Tourism  |
| <b>Division:</b> Operations  |
| <b>Building/Facility Location:</b> Colossal Cave Mountain Park<br>16721 E. Old Spanish Trail<br>Vail, AZ 85641 |
| <b>Contact Person:</b> Mike Holmes (520)247-4544, Economic Development & Tourism Requested Inspection          |

| Finding # | Description   | Reference                          | Location   | Photo  |
|-----------|---|------------------------------------|------------|--|
| 1.        | <p>First aid supplies are available for emergency use in the cave, which is a great best management practice. However, the tour staff is not certified in First Aid.</p> <p>Recommend that staff become certified in CPR and First Aid.</p>   | <b>Public Safety and Liability</b> | Basic Tour |   |
| 2.        | <p>First aid supplies are available for emergency use in the cave, which is a great best management practice. However, almost all supplies were past their expiration date (Eye drops, Exp: 3/2012).</p> <p>Recommend that a written check list for par level/expiration be instituted.</p> | <b>Public Safety and Liability</b> | Basic Tour |  |
| 3.        | <p>Abandoned mine shaft does not appear to be structurally sound.</p> <p>Recommend to have shaft evaluated by a Professional Engineer for potential ways to stabilize Mark area off to ensure public is kept away.</p>  | <b>Public Safety and Liability</b> | Mine Shaft |  |

|    |   |  |                    |  |
|----|---|--|--------------------|--|
| 4. | <p>Electric equipment shall be free from recognized hazards that are likely to cause death or serious physical harm to employees.</p> <p>Any open electrical should be properly encased. Identify parts that are no longer energized, and then have them removed or moved off path to eliminate trip hazards.</p> | <p><b>OSHA<br/>29CFR1910.303(b)(1)</b></p> <p><b>Public Safety and Liability</b></p> | Intermediate Trail |  |
| 5. | <p>Path to Intermediate trail has metal bar that extends past the rock.</p> <p>Recommended that this metal bar be removed or guarded to prevent injury.</p>   | <p><b>Public Safety and Liability</b></p>  | Intermediate Trail |  |

**Program Manager: Sarah Horvath**

**Signature:**

**Date: June 24, 2014**