

Route	From	To	Condition Rating	Treatment	Key
River	Stone Loop	La Canada (excludes COT)	Poor-Failed	Mill / Fill 2"	1
Oracle Foothills Estates	Subdivision		Poor-Failed	Structural Overlay 1.5"	2
Los Reales	Country Club	Alvernon	Failed	Structural Overlay 3"	3
Littletown 1 and 2	Subdivision		Poor-Failed	Structural Overlay 1.5"/Slurry	4
Wetmore	Highway Drive	La Cholla	Poor-Failed	Structural Overlay 2"	5
Drexel	Mission	Westover	Poor	Structural Overlay 2"	6
Western Way	Kinney		Failed	Mill / Fill 2"	7
Anway	Avra Valley	El Tiro	Failed	Structural Overlay 2"	8
Irrington	Cmo De Oeste	Sunset	Poor	Structural Overlay 2"	9
Abrego	Esperanza	Continental	Failed	Mill / Fill 2"	10
Houghton	Catalina Highway	Snyder	Failed	Structural Overlay 2"	11
49ers Entrance	Tanque Verde	Wagon Wheel	Failed	Mill / Fill 2"	12
Mission	250n CL Irrington Rd	250n CL Drexel Rd	Poor	Mill / Fill 2"	13
Camino De La Tierra	Valencia	Los Reales	Poor-Failed	Mill / Fill 2"	14


Pima County DOT Pavement Preservation Program: Spring Plan 2013

The information depicted on this display is the result of digital analyses performed on a variety of databases provided and maintained by several governmental agencies. The accuracy of the information presented is limited to the collective accuracy of these databases on the date of the analysis. Pima County Information Technology Department Geographic Information Systems makes no claims regarding the accuracy of the information depicted herein. This product is subject to the GIS Division Disclaimer and Use Restrictions.



GEOGRAPHIC INFORMATION SERVICES
 Pima County Information Technology Dept.
 201 North Stone Avenue - 9th Floor
 Tucson, Arizona 85701-1207
 (520)740-6670 - FAX: (520)798-3429

- Pavement Preservation
- Subdivision
- Jurisdiction Boundaries
- BOS Districts
- Major Streets



Scale 1:75,000

