R13E

T14S

T15S



Note: Aerial Photography By
Science Applications International Corporation (SAIC)
April, 1998

Paseo de Las Iglesias Geotechnical Report

PIMA COUNTY DEPARTMENT OF TRANSPORTATION
TECHNICAL SERVICES

Pima County Technical Services
201 North Stone Avenue - 9th Floor
Tucson, Arizona 85701-1207
(520)740-6670 - FAX:(520)798-3429
http://www.dot.co.pima.az.us

The information depicted on this display is the result of digital analyses performed on a variety of databases provided and maintained by several governmental agencies. The accuracy of the information presented is limited to the collective accuracy of these databases on the date of the analysis. The Pima County Department of Transportation Technical Services Division makes no claims regarding the accuracy of the information depicted herein.

This product is subject to the Department of Transportation Technical Services Division's Use Restriction Agreement.

- Washes
- Study Area
- Township and Range
- Section Lines
- ADWR Well Locations
- Sediment Sampling Locations

N

1000 3000 5000
0 2000 4000 Feet

wombat/special/ward/amls/iglesias1.aml

27-NOV-2001