

Figures

Fig. 2.1 Effluent Flow in 2010

Fig. 2.2 Annual Discharge at Cortaro Rd. and Trico Rd. from 1991 to 2011

Fig. 2.3 Annual Effluent at Roger Rd. and Ina Rd. WTFs from 1989 to 2011

Fig. 2.4 Fractional Annual Discharge at Cortaro Rd. and Trico Rd. from 1991 to 2011

Fig. 2.5 Mass Balance Conceptual Model

Fig. 2.6 Annual Losses, Cortaro Rd to Trico Rd. from 1991 to 2011

Fig. 2.7 Monthly Discharge at Cortaro Rd. and Trico Rd. from 1990 to 2011

Fig. 2.8 Mean Monthly Discharge at Cortaro Rd. and Trico Rd. from 1990 to 2011

Fig. 2.9 Monthly Losses, Cortaro Rd. to Trico Rd. from 1990 to 2011

Fig. 2.10 Monthly Discharge: Cortaro Rd. vs. Trico Rd. from 1990 to 2011

Fig. 2.11 Infiltration Rate Change Over Time (Lacher, 1996)

Fig. 2.12 Mean Daily Discharge at Cortaro Rd and Trico Rd Gauges, 1993

Fig. 2.13 Mean Daily Discharge at Cortaro Rd. and Trico Rd. Gauges, 2006

Fig. 2.14 Arizona Statewide Five-Year Average Winter Half Year (November to April) Precipitation, with the long term average five-year winter precipitation (Jacobs et al., 2005).

Fig. 2.15 Daily Discharge and 30-day Average Recharge

Fig. 2.16 Number of Events Exceeding Daily Average Discharge of 2,000 cfs

Fig. 2.17 Discharge at Cortaro Rd. Gauge from May 1 to June 30, 2012

Fig. 2.18 Discharge at Trico Rd. Gauge from May 1 to June 30, 2012

Fig. 2.19 Flows at Twin Peaks, Cortaro and Trico Roads

Fig. 2.20 Diurnal Effluent Discharge at the Ina Rd. WRF

Fig. 2.21 Diurnal Effluent Discharge at the Roger Rd. WRF

Fig. 3.1 Procedure to Evaluate Elevation Changes in Effluent Flow Channels

Fig. 3.2 Changes in Effluent Flow Channel Area

Fig. 3.3 Changes in Effluent Flow Channel Length

Fig. 3.4 Changes in Effluent Flow Channel Width

Fig. 3.5.1 Percentage of Total Area of Erosion and Deposition between 1998 and 2005

Fig. 3.5.2 Percentage of Total Area of Erosion and Deposition between 2005 and 2008

Fig. 3.6.1 Percentage of Total Area of Erosion and Deposition in a Floodplain between 1998 and 2005

Fig. 3.6.2 Percentage of Total Area of Erosion and Deposition in a Floodplain between 2005 and 2008

Fig. 3.7 Sediment Volume Changes in Effluent Flow Channel between 1998-2005 and 2005-2008

Fig. 3.8 Sediment Volume Changes in Floodplain between 1998-2005 and 2005-2008

Fig. 4.1 Sonoran Riparian Deciduous Forest (principally Goodding willows) and Strand along the LSCR

Fig. 4.2 Mesquite Woodland along the LSCR

Fig. 4.3 Saltbush, *Atriplex polycarpa*, along the LSCR near Ina Rd (Right)

Fig. 4.4 Saltbush Association, near Los Morteros, Santa Cruz River floodplain.

Fig. 4.5 Athel colonizing the former gravel pit located on Flood Control District property at the confluence of the Rillito River. August 2008 Santa Cruz River color imagery.

Fig. 4.6 State and transition model for Strand, March, Riparian Scrub, and Forest, Woodland and Floodplain Grassland plant communities

Fig. 5.1.1 Temporal changes in Nitrogen discharge at Roger Rd. WRF

Fig. 5.1.2 Temporal changes in Nitrogen discharge at Ina Rd. WRF

Fig. 5.2.1 Total Kjeldahl Nitrogen concentration near Cortaro Road

Fig. 5.2.2 Total Kjeldahl Nitrogen concentration at RWRD sampling sites

Fig. 5.3 Ammonia concentration near Cortaro Road

Fig. 5.4 Ammonia concentration at RWRD sampling sites

Fig. 5.5 Nitrate and Nitrite concentration near Cortaro Road

Fig. 5.6 Nitrate and Nitrite concentration at RWRD sampling sites

Fig. 5.7 Phosphorus concentration near Cortaro Road

Fig. 5.8 Dissolved oxygen concentration near Cortaro Road

Fig. 5.9 Dissolved oxygen concentration at RWRD sampling sites

Fig. 5.10 Total Dissolved Solid (TDS) near Cortaro Rd.

Fig. 5.11 Total Dissolved Solid (TDS) at RWRD sampling sites

Fig. 5.12 Temporal Changes in Major Ions (meq/l) near Cortaro Road

Fig. 5.13 Major Ions of Central Well Field and CAP Water

Fig. 5.14 Major Ion Concentrations at Outfalls (meq/l)

Fig. 5.15.1 Major Ion Concentrations (meq/l) at SC-03

Fig. 5.15.2 Major Ion Concentrations (meq/l) at SC-06

Fig. 5.15.3 Major Ion Concentrations (meq/l) at SC-12

Fig. 5.16 Sodium Adsorption Ratio (SAR) near Cortaro Road

Fig. 5.17 Average Sodium Adsorption Ratio near Cortaro Road

Fig. 5.18 Sodium Adsorption Ratio (SAR) at RWRD sampling sites

Fig. 5.19 pH measured near Cortaro Road

Fig. 5.20 Temperature measured near Cortaro Road

Fig. 7.1 Current Effluent Entitlement and Distribution (AFY: Acre-feet per year)

Fig. 3.2.2 Infiltration Rate Change Over Time

Fig. 3.2.3 Daily Discharge

Fig. 3.2.4 Number of Events Exceeding Daily Average of 2000 cfs

Fig. 3.2.5 Discharge at Cortaro Road Gauge from May 1 to June 30, 2012

Fig. 3.2.6 Discharge at Trico Road Gauge from May 1 to June 30, 2012

Fig. 3.2.7 Flows at Twin Peaks, Cortaro and Trico Roads

Fig. 3.3.1 Procedure to Evaluate Elevation Changes in Low Flow Channels

Fig. 3.3.2 Changes in Low Flow Channel Area

Fig. 3.3.3 Changes in Low Flow Channel Length

Fig. 3.3.4 Changes in Low Flow Channel Width

Fig. 3.3.5.1 Percentage of Total Area of Erosion and Deposition between 1998 and 2005

Fig. 3.3.5.2 Percentage of Total Area of Erosion and Deposition between 2005 and 2008

Fig. 3.3.6 Sediment Volume Changes between 1998-2005 and 2005-2008

Fig. 3.4.1.1 Sodium Adsorption Ratio (SAR) near Cortaro Road

Fig. 3.4.1.2 Average Sodium Adsorption Ratio near Cortaro Road

Fig. 3.4.2 Sodium Adsorption Ratio (SAR) at RWRD sampling sites

Fig. 3.4.3 Total Dissolved Solid (TDS) near Cortaro Road

Fig. 3.4.4 Total Dissolved Solid (TDS) at RWRD sampling sites

Fig. 3.4.5 Temporal Changes in Major Ions (meq/l) near Cortaro Road

Fig. 3.4.6 Major Ion Concentrations at Outfalls (meq/l)

Fig. 3.4.7a Major Ion Concentrations (meq/l) at SC-03

Fig. 3.4.7b Major Ion Concentrations (meq/l) at SC-06

Fig. 3.4.7c Major Ion Concentrations (meq/l) at SC-12

Fig. 3.4.8 Total Kjeldahl Nitrogen concentration near Cortaro Road

Fig. 3.4.9 Total Kjeldahl Nitrogen concentration at RWRD sampling sites

Fig. 3.4.10 Ammonia concentration near Cortaro Road

Fig. 3.4.11 Ammonia concentration at RWRD sampling sites

Fig. 3.4.12 Nitrate and Nitrite concentration near Cortaro Road

Fig. 3.4.13 Nitrate and Nitrite concentration at RWRD sampling sites

Fig. 3.4.14 Phosphorus concentration near Cortaro Road

Fig. 3.4.15 Dissolved oxygen concentration near Cortaro Road

Fig. 3.4.16 Dissolved oxygen concentration at RWRD sampling sites

Fig. 3.4.17 pH measured near Cortaro Road

Fig. 3.4.18 Temperature measured near Cortaro Road

Fig. 4.1.1 Modeling Results

Fig. 4.1.2 Modeling Results

Fig. 4.1.3 Modeling Results

Fig. 4.1.4 Modeling Results

Fig. 4.1.5 Peak Discharge Measured at Cortaro Gage

Fig. 4.1.6 Peak Discharge Measured at Trico Gage

Fig. 4.2.1 Site Visit Photograph 1

Fig. 4.2.2 Site Visit Photograph 2

Fig. 4.2.3 Site Visit Photograph 3

Fig. 4.2.4 Invert Change to Cross Section Distance: Engelund-Hansen/Toffaleti

Fig. 4.2.5 Invert Change to Cross Section Distance: Toffaleti/Report 12

Fig. 4.2.6 Invert Change to Cross Section Distance: Engelund-Hansen/Ruby

Fig. 4.2.7 Invert Change to Cross Section Distance: Toffaleti/Toffaleti

Fig. 4.2.8 Invert Change to Manning's Roughness Coefficient: Engelund-Hansen/Toffaleti

Fig. 4.2.9 Invert Change to Manning's Roughness Coefficient: Toffaleti/ Toffaleti

Fig. 4.2.10 Particle Size Distribution (INA; Ina Rd., AVR: Avra Valley, TRC: Trico Rd.)

Fig. 4.2.11 Invert Change: Engelund-Hansen/Ruby

Fig. 4.2.12 Invert Change: Toffaleti/Report 12

Fig. 4.2.13 Temperature Measured at Marana High Plains in 2011

Fig. 4.2.14 Average Temperature at RW

Fig. 5.1.1 Current Effluent Entitlement and Distribution (AFY: Acre-feet per year) RD Sampling Sites

Tables

Table 2.1 Monthly Mean Losses: Sorted (1990-2011)

Table 2.2 Annual Discharge, Infiltration and Percent Infiltration from 1991-1993

Table 2.3 Annual Discharge, Infiltration and Percent Infiltration from 2004-2011

Table 2.4 Flow Measurement at Twin Peaks and Cortaro Road

Table 3.1 Area of Effluent Flow in Reaches

Table 3.2 Length of Effluent Flow in Reaches

Table 3.3 Width of Effluent Flow in Reaches

Table 3.4.1 Percentage of Total Area of Erosion and Deposition between 1998 and 2005

Table 3.4.2 Percentage of Total Area of Erosion and Deposition between 2005 and 2008

Table 3.5.1 Largest Flood Peak at Cortaro Rd.

Table 3.5.2 Largest Flood Peak at Trico Rd.

Table 3.6.1 Mean Daily Discharge Exceeding 2,000 cfs at Cortaro Rd.

Table 3.6.2 Mean Daily Discharge Exceeding 2,000 cfs at Trico Rd.

Table 3.7 Summary of Results (*Red means "major" change, Blue means "minor" change, and No-Color means "moderate" change.*)

Table 5.1 Selected Water Quality Parameters

Table 5.2 Water Quality Data

Table 6.1 Comparison of Invertebrate Collection and Identification Methods

Table 6.2 Comparison of Invertebrates Reported from the Previous Studies

Table 7.1 Historical Influent and Effluent Volumes by Metropolitan Treatment Facility

Table 7.2 Existing Pollutant Removal Efficiency

Table 7.3 Existing and Anticipated Pollutant Concentration

