

Rillito River Linear Park: Alvernon to Craycroft Project

Rillito River flood photos, July 31, 2006



Photo 1 – Rillito River in flood



Photo 2 – Looking north at Swan Road and the Rillito Creek. Notice the inundation areas south of the left embankment.



Photo 3 – Looking northwest at the Rillito Creek and Alamo Wash confluence. Notice the inundation areas south of the left embankment.



Photo 4 - Rillito River in flood



Photo 5 – Looking northeast at Swan Road and the Rillito Creek. Notice the inundation areas south of the left embankment.



Photo 6 - Rillito River in flood



Photo 7 - Rillito River in flood



Photo 8 - Rillito River in flood



Photo 9 – A dead fish after a flood in the Rillito River



Photo 10 - Rillito River in flood



Photo 11 - Rillito River in flood



Photo 12 – A car flooded by flow that overtopped the bank of the Rillito River



Photo 13 - Rillito River in flood