

PIMA COUNTY REGIONAL FLOOD CONTROL DISTRICT INFRASTRUCTURE MAINTENANCE DIVISION

Inspection Form

Structure Type, Inspector, and Location Information

Field Inspection For:

Inspection Type: Complaint Pictometry - year: 2018 Post-storm Routine - annual Routine - 3 year

Inspector: Date/Time Field TRS:

Constructed drainageway Natural drainageway Watershed:

Primary Street: Secondary Street:

Overall Comments and Recommendations

Recommended Action: Engineering Maintenance Monitor None

General Observations

The bank protection at this section of the Santa Cruz River appears to be in working condition at this time. There are areas of overgrown vegetation along both banks. The flap gates and outlets at this section appear to be free of trash debris at this time.

Inspection Information - Overall Physical Processes

Erosion	<input checked="" type="checkbox"/>	Minimal	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	<input type="checkbox"/>	Not Applicable
Graffiti	<input checked="" type="checkbox"/>	Minimal	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	<input type="checkbox"/>	Not Applicable
Scour	<input checked="" type="checkbox"/>	Minimal	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	<input type="checkbox"/>	Not Applicable
Sediment	<input checked="" type="checkbox"/>	Minimal	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	<input type="checkbox"/>	Not Applicable
Standing Water	<input type="checkbox"/>	Minimal	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	<input checked="" type="checkbox"/>	Not Applicable
Trash or Debris	<input checked="" type="checkbox"/>	Minimal	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	<input type="checkbox"/>	Not Applicable
Vegetation Growth	<input checked="" type="checkbox"/>	Minimal	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	<input type="checkbox"/>	Not Applicable
Invasive Species*	<input type="checkbox"/>	Minimal	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	<input checked="" type="checkbox"/>	Not Applicable

*Invasive Species Coverage:

<input type="checkbox"/> Buffelgrass	<input style="width: 50px;" type="text"/>	%	<input type="checkbox"/> Arundo	<input style="width: 50px;" type="text"/>	%
<input type="checkbox"/> Fountaingrass	<input style="width: 50px;" type="text"/>	%	<input type="checkbox"/> Tamarisk	<input style="width: 50px;" type="text"/>	%
<input type="checkbox"/> Sahara Mustard	<input style="width: 50px;" type="text"/>	%	<input type="checkbox"/> Other _____	<input style="width: 50px;" type="text"/>	%



Photo # 6

Photo # 5

Photo # 4

Photo # 7

Photo # 8

Photo # 3

Photo # 2

Photo # 1

Photo # 9